

West Rainton Parish Council

WARNING: Extreme caution needed for personal safety.

Outcome of Memorial headstone safety testing

Following recent memorial headstone safety testing, those found to be **unstable** have now been identified with “warning tape”.

The Parish Council apologise for any distress.

Memorial owners affected must now contact a suitably qualified contractor to take swift action to have the necessary repairs carried out to British Standard 8415 and current industry codes of practice.

To comply with Health and Safety guidance, the Parish Council will lay flat any headstones not repaired by ***Date Month Year.***

Queries:

Email: westraintonparishcouncil@yahoo.co.uk or call 0794 120 4118

May 2017